



MITSUBISHI ROSA  
Stock ID 332928

Registration Year: 2005  
Manufacture Year: 0

## Vehicle Specifications

|                |      |                 |               |             |                   |           |        |
|----------------|------|-----------------|---------------|-------------|-------------------|-----------|--------|
| Model:         |      | Chassis No:     | BE63DE-400125 | Grade:      |                   | Fuel:     | Diesel |
| Engine:        | 4M50 | Drive Train:    | 2WD           | Dimensions: | 36 M <sup>3</sup> | Shape:    | BUS    |
| Engine No:     | 2023 | Transmission:   | MT            | Mileage:    | 301900            | Capacity: | 4890cc |
| Ext. Color:    |      | Weight (kg):    |               | Seats:      | 26                | Color:    |        |
| Certification: |      | Classification: |               | Exterior:   | WHITE             | Interior: | BEIGE  |

## Vehicle images



## Vehicle Options

|                |     |                   |     |                 |                        |               |     |
|----------------|-----|-------------------|-----|-----------------|------------------------|---------------|-----|
| Pwr Steering   | Yes | Pwr Wind          | Yes | Pwr Mirrors     | Center Lock            | Air Cond      | Yes |
| Reverse Camera |     | Pwr Slide Door    |     | Easy Closer     | Cruise Control         | ABS           |     |
| Air Bag        |     | Fog Lamps         |     | HID Head Lamps  | LED Head Lamps         | Spare Key     |     |
| Remote Key     |     | Push Start        |     | Seat Heater     | Pwr Seat               | Leather Seat  |     |
| Floor Mat      |     | Sun Roof          |     | Alloy Wheels    | Grill Guard            | Rear Wiper    |     |
| Rear Spoiler   |     | Stereo (FULL)     |     | Navi/TV         | CD Player              | Car MD        |     |
| AUX            |     | Spare Tire        |     | Spare Tire Case | Puncture Repairing Kit | Tool          |     |
| Jack           |     | Operators Manual  |     | Maint. Record   | 360 Degree Camera      | AM/FM Radio   | Yes |
| 4WD            |     | 2WD               | Yes | Back Tire       | TV                     | Body Kit      |     |
| Side Skirts    |     | Front Lip Spoiler |     | Turbo           | Side Airbag            | Wheel Spanner |     |
| ESC            |     | Keyless Entry     |     |                 |                        |               |     |

