TOYOTA HIACE AMBULANCE

Stock ID 503727

Vehicle Specifications

| Model: | | Chassis No: | JTFLA3CP106006091 | Grade: | AMBULANCE | Fuel: | Diesel |
|----------------|---------|-----------------|-------------------|-------------|-------------------|-----------|-------------|
| Engine: | 1GD-FTV | Drive Train: | 2WD | Dimensions: | 34 M ³ | Shape: | VAN |
| Engine No: | 2023 | Transmission: | AT | Mileage: | 182800 | Capacity: | 2800cc |
| Ext. Color: | | Weight (kg): | | Seats: | 6 | Color: | |
| Certification: | | Classification: | | Exterior: | WHITE RED | Interior: | BLACK BEIGE |

Vehicle images



Vehicle Options

| Pwr Steering | Yes | Pwr Wind | Yes | Pwr Mirrors | Yes | Center Lock | Yes | Air Cond | Yes |
|----------------|-----|-------------------|-----|-----------------|-----|------------------------|-----|---------------|-----|
| Reverse Camera | | Pwr Slide Door | | Easy Closer | | Cruise Control | | ABS | |
| Air Bag | Yes | Fog Lamps | | HID Head Lamps | | LED Head Lamps | | Spare Key | |
| Remote Key | | Push Start | | Seat Heater | | Pwr Seat | | Leather Seat | |
| Floor Mat | | Sun Roof | | Alloy Wheels | | Grill Guard | | Rear Wiper | |
| Rear Spoiler | | Stereo (FULL) | | Navi/TV | | CD Player | | Car MD | |
| AUX | | Spare Tire | | Spare Tire Case | | Puncture Repairing Kit | | Tool | |
| Jack | | Operators Manual | | Maint. Record | | 360 Degree Camera | | AM/FM Radio | Yes |
| 4WD | | 2WD | Yes | Back Tire | | TV | Yes | Body Kit | |
| Side Skirts | | Front Lip Spoiler | | Turbo | | Side Airbag | | Wheel Spanner | |
| ESC | | Keyless Entry | | | | | | | |